

ROAD CHECK – June 6 and 7, 2018 at 4:00 p.m.

1. 430th Avenue (Town Hall road)

Estimated Loads 20+ Actual Cost _____
2012 – 30, 2013 – 50, 2014 – 35, 2015 – 40, 2016 – 20, 2017 - 40
A. Dust Control.

2. 440th Avenue (Klump road)

Estimated Loads 0 Actual Cost _____
2012 – 5, 2013 – 5, 2014 – 3, 2015 – 0, 2016 – 5, 2017 - 7

3. 260th Street

Estimated Loads 8-10 Actual Cost _____
2012 – 6, 2013 – 8, 2014 – 8, 2015 – 0, 2016 – 15, 2017 - 10

4. 460th Avenue (Town Line N)

Estimated Loads 15 Actual Cost _____
2012 – 5, 2013 – 8, 2014 – 6, 2015 – 12, 2016 – 5, 2017 - 12

5. 275th Street E (Miller road)

Estimated Loads 15 Actual Cost _____
2012 – 12, 2013 – 15, 2014 – 15, 2015 – 15, 2016 – 15, 2017 - 15

6. 426th Avenue (Hanson Haven road)

Estimated Loads 0 Actual Cost _____
2012 – 3, 2013 – 2, 2014 – 3, 2015 – 3, 2016 – 0, 2017 - 6

7. 430th Avenue

Estimated Loads 10 Actual Cost _____
2012 – 5, 2013 – 5, 2014 – 10, 2015 – 10, 2016 – 10, 2017 – 10

8. 270th Street East

Estimated Loads 10 Actual Cost _____
2012 – 6, 2013 – 8, 2014 – 0, 2015 – 10, 2016 – 10, 2017 - 5

9. 270th Street W (Estes road)

Estimated Loads 0 Actual Cost _____
2012 – 6, 2013 – 8, 2014 – 0, 2015 – 4, 2016 – 0, 2017 - 0

10. 265th Street (Carter-Greene road)

Estimated Loads 10 Actual Cost _____
2012 – 6, 2013 – 8, 2014 – 10, 2015 – 10, 2016 – 5, 2017 - 0

11. 275th Street (Spanswick road)

Estimated Loads 5 Actual Cost _____
2011 – 3, 2012 – 3, 2013 – 3, 2014 – 5, 2015 – 8, 2016 – 5

12. Lake Ethel Road – BLACKTOP – 2003, Sand Seal – 2015, Patched – 2016

Work Needed _____ Actual Cost _____
A. MAYBE skim over patched areas.

13. El Will Road – 2002 reworked

Estimated Loads 10 Actual Cost _____
2012 – 6, 2013 – 6, 2014 – 6, 2015 – 15, 2016 – 5, 2017 - 12
A. Dust Control

14. Holiday Road

Estimated Loads 10 Actual Cost _____
2012 – 20, 2013 – 25, 2014 – 20, 2015 – 20, 2016 – 20, 2017 - 12
A. Dust Control.

15. Blanche Creek Road

Estimated Loads 5 Actual Cost _____
2012 – 4, 2013 – 6, 2014 – 6, 2015 – 6, 2016 – 8, 2017 - 8

16. Girard Beach Road – BLACKTOP – 10/2004, Sand Seal – 2015, Patched – 2016

Work Needed _____ Actual Cost _____
A. Fix hole near end with a bag of cold mix.

17. Garland Lane – BLACKTOP -10/2004, Sand Seal – 2015, Patched – 2016

Work Needed _____ Actual Cost _____
A. MAYBE skim low areas.

18. 244th Street

Estimated Loads 0 Actual Cost _____
2012 – 0, 2013 – 2, 2014 – 0, 2015 – 6, 2016 – 0, 2017 - 4

19. Beauty Shore Drive – BLACKTOP – 2002, Sand Seal – 2015, Patched - 2016

Work Needed _____ Actual Cost _____
A. Will fix and skim bad area.

20. Kimber Corner cut across

Estimated Loads 0 Actual Cost _____
2012 – 0, 2013 – 0, 2014 – 0, 2015 – 0, 2016 – 1, 2017 - 2

21. 423rd Avenue

Estimated Loads 12 Actual Cost _____
2012 – 15, 2013 – 15, 2014 – 15, 2015 – 15, 2016 – 10, 2017 - 15
A. Dust Control.

22. Grace Etta Road and 240th Street – BLACKTOP – 1996, Sand Seal – 2005, 2017

Work Needed _____ Actual Cost _____

A. Tree on 240th Street.

23. Clarissa Haven Drive – BLACKTOP – 2002, Sand Seal - 2015

Work Needed _____ Actual Cost _____

24. 415th Avenue – BLACKTOP – 1996, Sand Seal – 2005, 2017

Work Needed _____ Actual Cost _____

A. Needs shouldering at intersection with Co. Hwy 5.

B. Needs shouldering at intersection with Ukkelberg Drive.

25. Ukkelberg Drive – BLACKTOP – 1996, Sand Seal – 2005, 2017, Patched – 2016, 2017

Work Needed _____ Actual Cost _____

A. Needs shouldering by slough.

26. Ferncliff Road – BLACKTOP – 1996, Sand Seal – 2005, 2017, Patched – 2016

Work Needed _____ Actual Cost _____

27. Ferncliff Road West

Estimated Loads 12 Actual Cost _____

2012 – 10, 2013 – 12, 2014 – 12, 2015 – 15, 2016 – 15, 2017 - 12

28. Statesboro Drive

Estimated Loads 0 Actual Cost _____

2012 – 1, 2013 – 0, 2014 – 0, 2015 – 3, 2016 – 5, 2017 - 0

29. 220th Street – BLACKTOP – 1999, Sand Seal – 2005, 2017, Excavated – 2006,
Patched - 2017

Work Needed _____ Actual Cost _____

A. Needs shouldering before lake.

30. Chippewa Road – BLACKTOP – 1999, Sand Seal – 2005, 2017, Replace Culvert – 2015
Patched - 2016

Work Needed _____ Actual Cost _____

A. By #23083 fix with 2 – 3 bags cold mix.

31. Chippewa Trail – BLACKTOP – 1999, Sand Seal - 2010

Work Needed _____ Actual Cost _____

A. Needs shouldering.

32. Chippewa Way – Reworked - 2006

Estimated Loads 0 Actual Cost _____

2012 – 0, 2013 – 2, 2014 – 0, 2015 – 0, 2016 – 12, 2017 - 0

33. 460th Avenue (Town Line S)

Estimated Loads 25 Actual Cost _____

2012 – 20, 2013 – 30, 2014 – 30, 2015 – 30, 2016 – 30, 2017 - 30

34. Killdeer Trail

Estimated Loads 3 Actual Cost _____

2012 – 0, 2013 – 0, 2014 – 2, 2015 – 12, 2016 – 0, 2017 - 3

35. Killdeer Trail Turnaround

Estimated Loads 3 Actual Cost _____

2012 – 0, 2013 – 0, 2014 – 1, 2015 – 0, 2016 – 0, 2017 - 0

36. Brandborg Creek Road

Estimated Loads 20 Actual Cost _____
2012 – 15, 2013 – 20, 2014 – 20, 2015 – 24, 2016 – 20, 2017 - 20
A. Dust Control.
B. Check culvert.

37. Brandborg Creek Court

Estimated Loads 6 Actual Cost _____
2012 – 0, 2013 – 0, 2014 – 5, 2015 – 3, 2016 – 3, 2017 - 2

38. Liberty Lane – Cleared - 1997

Estimated Loads 2 Actual Cost _____
2012 – 5, 2013 – 3, 2014 – 6, 2015 – 8, 2016 – 5, 2017 - 5
A. Needs blading.
B. Fill washouts.

39. Liberty Lane Turnaround

Estimated Loads 1 Actual Cost _____
2012 – 0, 2013 – 0, 2014 – 0, 2015 – 2, 2016 – 0, 2017 - 0

40. 447th Street

Estimated Loads 12 Actual Cost _____
2012 – 10, 2013 – 12, 2014 – 12, 2015 – 12, 2016 – 6, 2017 – 10
A. Pull in corners on intersection with Castle Drive E.

41. Castle Trail

Estimated Loads 1 Actual Cost _____
2012 – 0, 2013 – 1, 2014 – 0, 2015 – 0, 2016 – 0, 2017 - 1

42. Castle Drive East (Rainbow)

Estimated Loads 6 Actual Cost _____

2011 – 8, 2012 – 0, 2013 – 6, 2014 – 0, 2015 – 8, 2016 – 6

A. Dust Control.

43. Blackjack Drive

Estimated Loads 8 Actual Cost _____

2012 – 0, 2013 – 6, 2014 – 6, 2015 – 8, 2016 – 7, 2017 - 6

A. Check 2 approaches at Greg LaPlante property.

1. Approach by lake needs to be seeded.

44. Caste Drive West

Estimated Loads 5 Actual Cost _____

2012 – 4, 2013 – 6, 2014 – 0, 2015 – 5, 2016 – 4, 2017 - 5

A. Dust Control

45. 227th Street and 435th Avenue

Estimated Loads 12 Actual Cost _____

2012 – 0, 2013 – 0, 2014 – 8, 2015 – 0, 2016 – 5, 2017 - 0

A. Needs gravel by new approach.

46. Liberty Drive, 440th Avenue, 230th Street – BLACKTOP - 1993, Seal Coat – 2002,
Sand Seal – 2013, Patched – 2016

Work Needed _____ Actual Cost _____

A. Needs shouldering.

47. Castle Drive (O’Meara)

Estimated Loads 7 Actual Cost _____

2012 – 6, 2013 – 6, 2014 – 8, 2015 – 10, 2016 – 6, 2017 - 5

48. Mason Lake Drive

Estimated Loads 0 Actual Cost _____
2012 – 0, 2013 – 2, 2014 – 4, 2015 – 0, 2016 – 5, 2017 - 0

49. 440th Avenue – Rip Rap - 2011

Estimated Loads 8 Actual Cost _____
2012 – 10, 2013 – 10, 2014 – 12, 2015 – 15, 2016 – 10, 2017 - 6

Minimum estimated number of loads:	Class 5	Loads	130 - 132
	Clay		
	Pit Run for fill		
	Black Dirt		
	Stock Pile		
	TOTAL:		130 - 132